









**A****B****C**



D



E



x 2


F




G




H




I



J




K




x 12  
(M3 x L5.5)

L




x 4  
(M3 x L5.5)

M




x 7  
(M3 x L6)




N










x 2




- ▶ Worldwide : [www.lg.com/id-manual](http://www.lg.com/id-manual)
- ▶ 한국 : [www.lgservice.co.kr](http://www.lgservice.co.kr)
- ▶ SuperSign : <http://partner.lge.com>
















1







1 = 1







2







A



180°


B






3


A-1




A-2



B-1




B-2






4




5






6




7






8




9












10



11









\* M F L 7 2 1 5 0 3 0 1 \*

(2505-REV03)

